

SECRET

Declassification Review by NGA/DoD

OUT56307

SECRET 292122Z

1965 JUL 29 21 31Z

25X1

1. CAMERA B 7 WAS USED IN MISSION 8033 FLOWN ON 28 JULY 1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD WHERE NOT DEGRADED BY HAZE.

B. 9R SIDE: BOTH FILM EDGES CONTAIN CAMERA ROLLER INDUCED STATIC DISCHARGES. THE OUTBOARD EDGE ALSO CONTAINS INTERMITTENT SMALL EDGE STATIC DISCHARGES. FRAME 1800 IS DEGRADED BY NUMEROUS PINHOLES AND SCRATCHES. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 1968.

C. 9L SIDE: INBOARD CAMERA ROLLER INDUCED STATIC DISCHARGES ARE PRESENT THROUGHOUT THE FILM. A HEAT SPLICE IS POSITIONED BETWEEN FRAMES 298/299 AND A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 809. FRAME 900 CONTAINS A HANDLING ABRASION.

D. BOTH SIDES: THE TITLED FRAMES ARE NUMBERED 0000 TO 2223.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.

3. POSITIVE

A. THE PI SUITABILITY IS GOOD IN CLOUD FREE AREAS.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS AND/OR HAZE OBSCURE OR DEGRADE APPROXIMATELY 60 PERCENT OF THE TERRAIN COVERED IN THIS MISSION.

SECRET**SECRET**
-EN MESSAGE-

30 JUL 1965

COPIES RECEIVED		
No.	Office	Act.
	File	
	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
3,4	TID	
	PID	
	PAG	
	CLASS 4	
	AC	
	MAIL	